




## BILLY GOAT KV SHREDDER KIT (P/N 891153)

### INSTALLATION:

1. Disconnect spark plug wire.
2. Using a drift punch and hammer remove the two indented holes on the housing (see picture below).
3. Insert the shredder screen then place the bracket on the outside of the chute.
4. Secure the screen tightly with the knobs and nuts.
5. Pull the engine rope to make sure that the impeller does not come into contact with the screen.
6. If the impeller clears during rotation reconnect the spark plug wire.
7. When the shredder screen is not needed replace it with the plug.



Use a drift punch and hammer to remove these two holes.

Item	Part #	Description	Qty
1	890211	PLATE SHREDDER WA	1
2	890212	PLATE PLUG SHREDDER WA	1
3	430307	PLATE HANDLE SUPPORT	1
4	900456	KNOB LOCKING 5/16-18	2
5	8160002	NUT LOCK 5/16-18	2